




W O R K P R O®

FLEX

COLLECTION

CONNECTOR
GANGING SET

ENSEMBLE DE PLAQUES
D'ASSEMBLAG




WorkPro is a registered trademark of OMX, Inc
© 2016 Office Depot, Inc. All Rights Reserved.
If you have any questions, please call 800-949-9974.
Distributed by / Distribué par:
Swinton Avenue Trading Ltd., Inc.
6600 North Military Trail, Boca Raton, FL 33496 USA1
Made in USA / Fabriqué aux É.-U.


Assembly instructions and warranty information
Instructions pour l'assemblage et information sur la garantie

986-349
25326120
version 0416


Required tools
Outils requis




Possible configurations
Configurations possibles



- A Gang Connector (2X)**/ Connecteur d'assemblage (2X)
B Post (2X)/ Écrou de montage (2X)
C Self-tapping Screw (2X)/ Vis autotaraudeuse (2X)
D Marking Template Tool (1X)/ Outil de marquage (1X)



1



CAUTION! / MISE EN GARDE!

2 persons required to flip tables over on a protective surface to prevent scratching


2 personnes requises pour retourner les tables sur une surface protectrice afin d'éviter les risques de rayures.

2

Pierce table with marking template tool:

On the underside of the tables line up center groove on marking tool with meeting point of two tables. Strike the marking tool with a hammer to pierce the underside of the tables.


Percez la table avec l'outil de marquage :




3

Attach mounting post and self-tapping screws to underside of table

Attachez l'écrou de montage et les vis autotaraudeuses sur le dessous de la table



4




CAUTION! / MISE EN GARDE!

2 persons required to flip tables upright
2 personnes requises pour remettre les tables dans le bon sens

5

Attach Gang Connector to mounted posts by snapping into place

Attachez le connecteur d'assemblage avec les écrous de montage en le forçant en place



6

Connected underside of tables

Dessous des tables une fois connectées





WORKPRO®

LEG SET 143571


FIXED HEIGHT INSTRUCTIONS

Required tools




Limited Lifetime Warranty

Supports up to 500 lbs, evenly distributed across table top




- A** Table Top (1X)
- B** ARC T-Leg (2X)
- C** Mounting Plate (2X)
- D** Machine Screw (26X)
- E** Levelers (4X)




1

Attach levelers (4X)



2

Attach mounting plates to underside of table




CAUTION !

Set tabletop upside down on protected surface


3

Attach legs with machine screws



4

Set table upright



CAUTION !

2 persons required to flip table over



WORKPRO®

LEG SET 357114


ADJUSTABLE-HEIGHT INSTRUCTIONS

Required tools




Limited Lifetime Warranty

Supports up to 500 lbs, evenly distributed across table top




- A Table Top (1X)
- B ARC T-Leg (2X)
- C Adjustable Leg (2X)
- D Mounting Plate (2X)
- E Machine Screw (26X)
- F Levelers (4X)



1

Attach adjustable leg and set height


Attach levelers (4X)



CAUTION !
Adjust legs to desired height before attaching to table top

2


Attach mounting plates to underside of table



CAUTION !
Set tabletop upside down on protected surface


3

Attach legs with machine screws



4

Set table upright



Adjusts Top from 30" to 42" H

CAUTION !
2 persons required to flip table over
Always remove items from table before adjusting height
2 persons required to adjust both legs at the same time



WORKPRO®

LEG SET 812388


LOCKED-CASTER INSTRUCTIONS

Required tools




Limited Lifetime Warranty


Supports up to 500 lbs, evenly distributed across table top



- A Table Top (1X)
- B ARC T-Leg (2X)
- C Mounting Plate (2X)
- D Machine Screw (26X)
- E Caster (2X)
- F Caster w/Brake (2X)




1 Attach mounting plates to underside of table




CAUTION !

Set tabletop upside down on protected surface


2 Attach legs with machine screws



3 Attach (1X) locking caster and (1X) non-locking caster per leg.



4 Set table upright



CAUTION !

2 persons required to flip table over