




W O R K P R O®

FLEX

COLLECTION

CONNECTOR
GANGING SET

ENSEMBLE DE PLAQUES
D'ASSEMBLAG




WorkPro is a registered trademark of OMX, Inc
© 2016 Office Depot, Inc. All Rights Reserved.
If you have any questions, please call 800-949-9974.
Distributed by / Distribué par:
Swinton Avenue Trading Ltd., Inc.
6600 North Military Trail, Boca Raton, FL 33496 USA1
Made in USA / Fabriqué aux É.-U.


Assembly instructions and warranty information
Instructions pour l'assemblage et information sur la garantie

986-349
25326120
version 0416


Required tools
Outils requis




Possible configurations
Configurations possibles



- A Gang Connector (2X)**/ Connecteur d'assemblage (2X)
B Post (2X)/ Écrou de montage (2X)
C Self-tapping Screw (2X)/ Vis autotaraudeuse (2X)
D Marking Template Tool (1X)/ Outil de marquage (1X)



1



CAUTION! / MISE EN GARDE!

2 persons required to flip tables over on a protective surface to prevent scratching


2 personnes requises pour retourner les tables sur une surface protectrice afin d'éviter les risques de rayures.

2

Pierce table with marking template tool:

On the underside of the tables line up center groove on marking tool with meeting point of two tables. Strike the marking tool with a hammer to pierce the underside of the tables.


Percez la table avec l'outil de marquage :




3

Attach mounting post and self-tapping screws to underside of table

Attachez l'écrou de montage et les vis autotaraudeuses sur le dessous de la table



4




CAUTION! / MISE EN GARDE!

2 persons required to flip tables upright
2 personnes requises pour remettre les tables dans le bon sens

5

Attach Gang Connector to mounted posts by snapping into place

Attachez le connecteur d'assemblage avec les écrous de montage en le forçant en place



6

Connected underside of tables

Dessous des tables une fois connectées

